

INITIALISATION ROUTINES

Read from UART
Line Status Register

Is Data in Rx Latch?

Process input user character

Get DAC Status

Is FIFO Empty

Fill fifo with sound data

Process User input

Has command been
fully received

Process command

